



# INSTALLATION INSTRUCTIONS

## 50 Ohm CONNECTORS

Kabelwerk

**EUPEN** AG

E1016-Rev04/2007-04-02

cable

### 1/2" X (1/2" HIFLEX) - STRAIGHT CONNECTORS



1/2"X	<b>SPTC50B12X</b>

	NF, NM	7/16M	7/16F
	2 x 19 mm	19 mm & 21 mm & 32 mm	19 mm & 21 mm



### PREPARATION TOOL METHOD

**1** Cut the cable with side cutters.

**2** Strip the outer jacket with a utility knife. SPTC50B12X

**3** Strip the inner insulation. Dimensions: 10 mm (0.390") and 9.5 mm (0.370").

**4** Clean the conductors with 3M: F 04/013 abrasive.

**5** Apply Vaseline to the conductors.

**6** Insert the conductors into the connector. Dimensions: 7 mm (0.27"). Click.

**7** Tighten the connector nut.

**8**

**9** Tighten to 27 Nm (20 ft-lb).

**10** Final view of the connector.

Preparation drawing: 1:1

For any questions please contact KABELWERK EUPEN AG / for US Customer service call 1-800-419-5100

**NOTICE:**  
KABELWERK EUPEN AG disclaims any liability or responsibility for the results of improper or unsafe installation practices.

**AVIS:**  
KABELWERK EUPEN AG décline toute responsabilité en cas de non respect de ces instructions.

**WAARSCHUWING:**  
KABELWERK EUPEN AG wijst elke verantwoordelijkheid van de hand in geval van het niet opvolgen van deze aanbevelingen.

**BEMERKUNG:**  
KABELWERK EUPEN AG lehnt jede Verantwortung bei Nichtbeachtung dieser Instruktionen ab.

**AVISO:**  
KABELWERK EUPEN AG rehusa todas las responsabilidades en caso de no respetar las instrucciones.

**注意:**  
本公司声明对于不恰当或不安全的安装, 检验, 维修或拆卸操作所导致的后果不负任何义务和责任。

